

### Abstract

Ferrous articles are austenitized, then converted to at least 60% bainite, and the balance substantially converted to martensite; the  
5 articles are then cold worked, preferably by both compression and tensile deformation to at least 60% yield strength. The articles have improved serviceability, particularly fatigue life.

REF ID: A66003